Assembly Instructions / Pennant Holder



Screw the stabilizer element under the half sphere with a flat screwdriver.

2

Screw a tube into the half sphere and a second tube into the first one.

3

Place the upper part of the visual on the tube,

gently tighten

Fig A: Visual without the sleeve.

Visual not provided.

Fig B: Visual with a sleeve.

Visual not provided.



If you want the components to be locked, use the threadlocker sold on www.e-spheria.com



